

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0242/2022/JT
DATE : 29-Mar-22
WIP : 17307

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIU HUILING
ADDRESS : 26 JAMBOL PLACE
SINGAPORE 119353
TELEPHONE : HP +65 98311226
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210084009
VEHICLE NO : SNB 1570 M
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 30/7/2021
ENGINE NO : CZD C 45197
CHASSIS NO : WAUZZZF39M1146798
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Mar-22
PLACE OF ACCIDENT : SUOTH BUONA VISTA ROAD

PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1570 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF RHS FRONT DOOR.	S/N \$ 280.00	X
4	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	/ ✓
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 2,040.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : JORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1570 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	150 ✓
7	TO DISMANTLE AND RENEW FORNT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1400 1250 ✓
8	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT DOOR AND RHS UPPER A-PILLAR.	\$ 5,000.00	1100 ✓
9	TO CARRY OUT CLEAN UP FOR INTERIOR.	S/N \$ 480.00	✓
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,112.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1570 M

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER X NN	1	\$	1,073.00		
2	FRONT BUMPER SPOILER X NN	1	\$	426.00		
3	FRONT BUMPER GUIDE SECTION - RH X NN	1	\$	43.00		
4	FRONT FENDER - RH / 00	1	\$	1,445.00	✓	1156.00
5	FRONT FENDER ATTACHMENT PARTS X NN	1	\$	66.00		
6	FRONT FENDER BRACE - RH X NN	1	\$	98.00		
7	FRONT FENDER BRACKET - RH X NN	1	\$	39.00		
8	FRONT WHEEL HOUSING LINER - RH X NN	1	\$	260.00		
9	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X NN	1	\$	105.00		
10	FRONT FENDER COVER - RH X NN	1	\$	18.00		
11	HEADLIGHT MOUNTING - RH X NN	1	\$	132.00		
12	HEADLIGHT - RH X NN	1	\$	5,952.00		
13	BONNET X R	1	\$	3,695.00		
14	BONNET IMPACT PROTECTION - CENTER X NN	1	\$	31.00		
15	BONNET HINGE - LH / RH X NN	2	\$	162.00		
16	BONNET WHEEL ARCH COVER - LH / RH X BR	2	\$	566.00	✓	452.00
17	FRONT WINDSCREEN / BR	1	\$	1,246.00	✓	996.80
18	RAIN SENSOR GEL FOIL / MC	1	\$	130.00	✓	104.00
19	PRIMER / MC	1	\$	22.00	✓	17.36
20	AERO WIPER ARM - LH / RH X NN	2	\$	239.00		
SUB TOTAL SPARE PARTS			:	\$	15,748.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NOTAGUAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1570 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PA S/NETT
21	AERODYNAMIC WIPER BLADES / NT	1 \$	103.00 ✓ 82.40
22	FRONT WINDSCREEN WATER DEFLECTOR STRIP - RH X NN	1 \$	52.00
23	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH OUTER X NN	1 \$	251.00
24	FRONT DOOR WINDOW GUIDE TRIM STRIP - RH X NN	1 \$	287.00
25	FRONT DOOR CORNER TRIM - RH X NN	1 \$	51.00
26	FRONT WINDSCREEN SEALANT / RC	S/N \$	200.00 ✓ 200.00
27	SUNDRIES ? NEC	\$	300.00 21.60 ✓
TOTAL SPARE PARTS		:	\$ 16,992.00
TOTAL LABOUR CHARGES		:	\$ 11,112.00
GRAND TOTAL		:	\$ 28,104.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Steve (LKK)
30/3/22, 12.30 PM

OD - M AL
Excess - ?
P/P
My BL by
5 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT