



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS/AIS22002953/Aqy3n2

Date: 26/05/2022

Code: AIS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNB 9906B	Veh. Inspected	GBF 1837R
Policy No.		Coverage (\$)	0.00
Claim No.	2022 22004342SL	Excess (\$)	0.00
Assign From	GERMAINE LEONG	Assign Date	30/03/2022

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1SC2F24Z0858815	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12C	YOKOHAMA	6 mm
L/H Rear Tyre	155 R12C	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/03/2022	Inspection Date	30/03/2022
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
--	-----------------------