

SJE :

Date of Survey : _____

Date of ReSurvey: _____ **After-Paint:** _____

Contacts : _____

Vehicle Nos : **SJQ 1003 C**

Model : Toyota Altis

Year : 2009

Chassis No : MR053ZEE106144070

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bonnet	1	\$ 796.90	\$ 796.90	DDV
2	Bonnet inner lock	1	\$ 148.00	\$ 148.00	JMV
3	Bonnet hinge	1	\$ 78.00	\$ 78.00	BTV
4	Bonnet insulator	1	\$ 158.30	158.30	NDX
5	Front bumper	1	\$ 586.20	\$ 586.20	BRV
6	Front bumper side retainer	2	\$ 85.25	\$ 170.50	NECV
7	Front bumper inner sponge	1	\$ 195.40	195.40	NNX
8	Front bumper reinforcement	1	\$ 489.60	489.60	NDX
9	Front bumper fog lamp	RH 1	\$ 186.20	\$ 372.40	BRV
10	Front bumper fog lamp garnish	RH 1	\$ 102.40	204.80	BRV
11	Front bumper lower grille	1	\$ 190.20	190.20	CRAV
12	Front grille assy	1	\$ 515.00	\$ 515.00	CRAV
13	Front grille logo	1	\$ 78.00	\$ 78.00	NECV
14	Front support panel	1	\$ 862.70	\$ 862.70	BTV
15	Front support panel top garnish	1	\$ 248.60	248.60	NNX
16	Front fender	RH 1	\$ 898.10	\$ 1,796.20	DDV
17	Front fender inner cowling	2	\$ 249.20	498.40	NDX
18	Front fender emblem 'DUAL VVTI'	2	\$ 77.50	\$ 155.00	NECV
19	Front door RH	1	\$ 1,615.90	1,615.90	DDX
20	Front door black tape	1	\$ 85.30	85.30	NNX
21	Front door inner lock	1	\$ 577.20	577.20	NNX
22	Headlamp	2	\$ 890.40	\$ 1,780.80	BRV
23	Headlamp lower bracket	2	\$ 105.00	210.00	NNX
24	Headlamp panel	RH 1	\$ 298.00	\$ 596.00	DDV
25	Radiator	1	\$ 1,651.90	\$ 1,651.90	DDV
26	Radiator top bracket	2	\$ 45.00	\$ 90.00	NECV
27	Radiator fan motor	1	\$ 358.00	358.00	NDV
28	Radiator fan cowling	1	\$ 445.00	\$ 445.00	BRV
29	Radiator fan blade	1	\$ 210.00	\$ 210.00	
30	Radiator top hose	1	\$ 180.00	180.00	NDX
31	Radiator lower hose	1	\$ 180.00	180.00	
32	Radiator spare tank	1	\$ 166.30	\$ 166.30	DDV
33	Aircon condenser	1	\$ 1,289.60	\$ 1,289.60	BTV
34	Aircon suction hose	1	\$ 320.00	\$ 320.00	NECV
35	Aircon discharge hose	1	\$ 384.00	\$ 384.00	

36	Wiper washer tank		1	\$	357.60	\$	357.60	DI
37	Wiper washer tank motor		1	\$	181.00	\$	181.00	NI
38	Wiper outer garnish		1	\$	388.65	\$	388.65	BA
39	Front windscreen		1	\$	1,087.60	\$	1,087.60	CA
40	Front windscreen moulding		1	\$	241.00	\$	241.00	NE
41	ABS pump assy		1	\$	1,758.30	\$	1,758.30	BR
42	Bootlid		1	\$	894.70	\$	894.70	DD
43	Bootlid logo		1	\$	85.50	\$	85.50	} Ni
44	Bootlid emblem 'COROLLA'		1	\$	68.00	\$	68.00	
45	Bootlid emblem 'ALTIS'		1	\$	65.37	\$	65.37	
46	Bootlid emblem '1.6'		1	\$	41.50	\$	41.50	
47	Bootlid emblem 'LX'		1	\$	48.80	\$	48.80	
48	Bootlid outer chrome garnish		1	\$	274.80	\$	274.80	CRM
49	Bootlid number plate lamp		2	\$	95.50	\$	191.00	ND
50	Bootlid lamp		2	\$	485.30	\$	970.60	BRV
51	Bootlid inner lock		1	\$	298.70	\$	298.70	JM
52	Bootlid inner lock striker		1	\$	65.00	\$	65.00	ND
53	Bootlid inner trim board		1	\$	352.80	\$	352.80	NDX
54	Bootlid weatherstrip		1	\$	298.60	\$	298.60	TNV
55	Bootlid hinge		2	\$	188.30	\$	376.60	NDX
56	Rear bumper		1	\$	785.90	\$	785.90	BRV
57	Rear bumper side bracket		2	\$	185.60	\$	371.20	BTV
58	Rear bumper reflector		2	\$	93.60	\$	187.20	BRV
59	Rear end panel		1	\$	762.10	\$	762.10	DDV
60	Rear end panel top garnish		1	\$	268.00	\$	268.00	BRV
61	Spare tyre panel		1	\$	837.70	\$	837.70	DDV
62	Spare tyre panel top board		1	\$	498.00	\$	498.00	BRV
63	Spare tyre panel fastener		1	\$	180.00	\$	180.00	BTV
64	Rear chassis RH		1	\$	889.00	\$	889.00	BTV
65	Rear fender RH		1	\$	827.90	\$	827.90	DDV
66	Rear fender inner trim board		2	\$	448.00	\$	896.00	TNV
67	Rear fender inner cowling RH		1	\$	124.00	\$	124.00	TNV
68	Rear windscreen moulding		1	\$	266.70	\$	266.70	NECV
69	Rear air vents		1	\$	62.30	\$	62.30	MISV
70	Rear door		1	\$	927.00	\$	927.00	GTXF
71	Rear door black tape		1	\$	108.00	\$	108.00	NRX
72	Rear door inner lock		1	\$	415.40	\$	415.40	} NN
73	Rear door inner lock sticker		1	\$	85.30	\$	85.30	
74	Rear door weatherstrip		1	\$	287.90	\$	287.90	
75	Taillamp		2	\$	594.60	\$	1,189.20	BRV
76	Taillamp lower bracket		2	\$	82.00	\$	164.00	MISV
77	Taillamp base panel	RH 1	2	\$	199.60	\$	399.20	DDV
78	Rear fuel tank		1	\$	1,187.30	\$	1,187.30	DDV
79	Rear axle		1	\$	1,045.00	\$	1,045.00	BTV
80	Rear shock absorber RH		1	\$	445.00	\$	445.00	BTV
81	Rear wheel bearing RH		1	\$	378.20	\$	378.20	JMV

