



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22002973/Bty3e2 Date: 31/05/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 4566Y	Veh. Inspected	SJQ 1003C
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/03/22/2070	Excess (\$)	0.00
Assign From	ASHLENE LEE	Assign Date	31/03/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053ZEE106144070	Colour	SILVER
Odometer	179356 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MATREX	4 mm
L/H Front Tyre	195/65 R15	MATREX	4 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	4 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/03/2022	Inspection Date	31/03/2022
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		24 Working Days	