

OPTIMA WERKZ

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

© /OptimaWerkz

Date: 28/03/2022
Vehicle No: SNE3041U
Model: TOYOTA COROLLA ALTIS HYBRID ELEGANCE
Chassis: MR2BZ3BE700008646-2021
Reg. Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMC5169U
Date of Accident: 25/03/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH 1150	1		PA \$1,335.00
2	FRONT DOOR INNER TRIM BOARD LH 980	1		myom \$1,215.00
3	REAR DOOR LH 1100	1		PA \$1,134.00
4	REAR DOOR INNER TRIM BOARD LH	1		PA \$1,011.00
5	REAR DOOR UPPER HINGE LH	1		R \$104.00
6	REAR DOOR LOWER HINGE LH	1		R \$125.00
7	REAR DOOR CHECKER LH	1		R \$194.00
8	REAR DOOR REGULATOR LH	1		Dis/In \$392.00
9	SIDE SKIRT LH	1		R SK \$633.00
10	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$6,143.00
LESS 25%				-\$1,535.75
PARTS TOTAL				\$4,607.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM CLIPS LH	1		RM \$50.00
2	REAR DOOR INNER TRIM CLIPS RH	1		RM \$50.00
3	SIDE SKIRT CLIPS LH	1		RM \$40.00
S/N TOTAL				\$140.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,000.00 500

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, SIDE SKIRT LH, REAR FENDER LH & ETC.

\$1,000.00 800

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.

\$120.00 60

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR LH.

\$120.00 60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



1) Date/Time, File Return to?

Add Fee:

Interview (\$

Tech Invs (\$

File

Others

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

o /OptimaWerkz

Date: 28/03/2022
Vehicle No: SNE3041U
Model: TOYOTA COROLLA ALTIS HYBRID ELEGANCE
Chassis: MR2BZ3BE700008646-2021
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SMC5169U
Date of Accident: 25/03/2022
Estimator: TING AN
Surveyor:

TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

\$120.00 201

LABOUR TOTAL \$2,360.00

TING AN

TOTAL

\$7,107.25

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Ching Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Add Fee:

- ☐ Interview
☐ Tech Invs (\$
☐ Weekend (\$