



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg No: 198003963G

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

Page 1 / 2

ESTIMATE

Date : 30/03/2022
To : LONPAC INSURANCE BHD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : LIEWSIMING
Office / Mobile :
Email / Fax No. : LiewSIMing@goldbell.com.sg

Reg No : XE6910Z
Model : FV70HJD2VDEA (C/C)
Chassis No : FV70HJA00212
Engine No : 470912C0504456
Quotation No. : 153440
Ref. No. : GBE/SVC/SALES-HQ/34-2603
D.O.A. : 26/03/2022
Policy No. : DMCVSNA00048872101
Claim Type : TP CLAIM - LONPAC
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		PANEL ASSY,FR DOOR,RH <i>buc</i>	1	3,265.58	0	3,265.58	3,265.58
2		UPP HINGE,FR DOOR?	1	261.64	0	261.64	261.64
3		LOWER HINGE,FR DOOR?	1	261.64	0	261.64	261.64
4		RUNCHANNEL,FR DOOR WINDOW GLASS,RH <i>X nn</i>	1	364.41	0	364.41	364.41
5		WEATHERSTRIP,FR DOOR OPENING,INR RH <i>nn</i>	1	491.45	0	491.45	491.45
6		MARK,BLUETEC <i>nn</i>	1	44.83	0	44.83	44.83
7		DECAL,SHIFT PILOT <i>nn</i>	1	14.99	0	14.99	14.99
8		PANEL,CAB FR CORNER,RH <i>de</i>	1	782.49	0	782.49	782.49
9		WEATHERSTRIP,CAB FR CORNER PANEL (LONG) <i>nn</i>	1	91.11	0	91.11	91.11
10		WEATHERSTRIP,CAB FR CORNER PANEL (SHORT) <i>nn</i>	1	28.82	0	28.82	28.82
11		PROTECTOR,FR PILLAR GARNISH EDGE <i>X nn</i>	1	72.89	0	72.89	72.89
PARTS TOTAL :							5,679.85

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC <i>600</i>	<i>1000</i> 600 1800.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	<i>60</i> 180 180.00
3	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM,ETC	<i>100</i> 700 700.00
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC <i>@ 350</i>	<i>500</i> 1050 1050.00

LABOUR TOTAL : 3,730.00
SUB-TOTAL : 9,409.85
GST @ 7% for \$ 9,409.85 658.69
GRAND TOTAL (S\$) : 10,068.54



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3678
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 199003963G

Page 2 / 2

ESTIMATE

Date	: 30/03/2022	Reg No	: XE6910Z
To	: LONPAC INSURANCE BHD.	Model	: FV70HJD2VDEA (C/C)
Attn.	:	Chassis No	: FV70HJA00212
Office / Mobile	:	Engine No	: 470912C0504456
Email Address	:	Quotation No.	: 153440
		Ref. No.	: GBE/SVC/SALES-HQ/34-2603
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 26/03/2022
Attn.	: LIEWSIMING	Policy No.	: DMCVSNA00048872101
Office / Mobile	:	Claim Type	: TP CLAIM - LONPAC
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : LIEWSIMING

DATE / TIME : 01/04/22 @ 1130

SURVEYOR : RASUL

MOBILE NO : 90010068

OFFICE FAX NO : 62567581

EMAIL ADDRESS : rasul@lkkauto.com

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 4 days

REMARKS : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

