

TPX5898

KAWA 2800

S H 22

- 1) Front Rim ✓ ~~880~~ ^{Best}
 2) Front wheel shaft ✓ ~~848~~ ^{Best} ✓
 3) Front brake disc LSR (NE Braking disc) ✓ ~~8720~~ X NE NEC
 4) Front Axle slider RSG ✓ ~~8120~~ ut ✓
 5) Front mugger ✓ ~~8220~~ ✓ cracked.
 6) Front fork complete set LSR ✓ ~~82800~~ ✓
 7) Steering stem ✓ ~~8480~~ ³⁸⁰ ✓ } NEC
 8) Steering cone bearing ~~8220~~ ✓
 9) Steering Tip Yoke ✓ ~~8300~~ ✓ and.
 10) Headlamp ✓ ~~8495~~ ✓ cracked.
 11) Head fairing ✓ ~~8210~~ ✓ cracked.
 12) Windscreen (RSG) ✓ ~~8210~~ ✓ cracked.
 13) Front signal LSR (1050) ✓ ~~898~~ X NE NEC
 14) Head cowling carbon cover LSR ✓ ~~8260~~ ✓ ut.
 15) ~~Front mugger "black"~~
 16) Handle bar ✓ ~~8175~~ ✓ ^{Best}
 17) Handguard lever LSR ✓ ~~898~~ ✓ ut.
 18) Brembo RCS clutch mount bracket ✓ ~~828~~ ✓ cracked.
 19) mirror LSR ✓ ~~8140~~ ✓ and.
 20) Frame sildace "RSG" ✓ ~~8195~~ ✓ ut. ^{300.}
 21) Rear fairing LSR "black" whole per ~~8395~~ ✓ cracked.
 22) ~~Rear center fairing "black"~~
 23) Rear number plate ✓ ~~840~~ X NE NEC
 24) Rear number tail tidy bracket ✓ ~~8120~~ X NE NEC
 25) magneto cover "RSG" ✓ ~~8160~~ X NE NEC
 26) Brembo RCS16 clutch ✓ ~~8495~~ ^{2nd} ✓
 27) fuel tank lower right fairing "black" ✓ ~~8240~~ ✓ ^{2nd}
 28) fuel tank cover LSR "matt black" ✓ ~~8260~~ X NE NEC
 29) fuel tank (Kawasaki emblem LSR) ✓ ~~872~~ ✓ NEC
 30) Tow ✓ ~~860~~ 40
 31) labour ✓ ~~8580~~ 400 740
 32) Spray Painting ~~\$400~~ 200
 33) To straighten body chassis ~~300~~ 100 (6 HK)

Like Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display images parts for resurvey
- Parts prices are subject to change
- Third party survey is on a "no fault" advice basis
- No illegal modifications is allowed
- Supply of parts is subject to availability

Acknowledged by Repairer

Signature:

Date:

8081

7272.90

total: 8012.90

4/5: 6.4K 05 Days.