

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 22 Apr 2022

## **Preliminary Advice**

Vehicle No	: SMR3647R	Accident Date	: 27/03/2022
Make	: TOYOTA PRIUS	Policy No.	: 102726
Assignment Date	: 01/04/2022	Excess	: S\$1,500.00
Date of Inspection	: 01/04/2022	Est. Duration of Repair	: 6
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 20,791.61
Revised Amount	:S\$ 11,774.59
Check Items (Estimated)	:S\$ 6,275.34
Total	:S\$ 18,049.93
Lump Sum Repair	:S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 112,000.00
COE / PARF Rebate	:S\$ 44,511.00
Salvage Value	:S\$

Margin for Repair

:S\$ 67,489.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.