

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan, Bennie-WZ

Date: 01 Apr 2022

Preliminary Advice

Vehicle No	: SBN8881Z	Accident Date	: 25/03/2022
Make	: AUDI Q5 SPORT	Policy No.	: 1800055715-03
Assignment Date	: 01/04/2022	Excess	: S\$0.00
Date of Inspection	: 31/3/2022	Est. Duration of Repair	: 14
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	48,661.00
Revised Amount	:S\$	35,735.00
Check Items (Estimated)	:S\$	1,508.00
Total	:S\$	37,243.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	64,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,196.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .