

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Apr 2022

Preliminary Advice

Vehicle No	: SMX616T	Accident Date	: 24/03/2022
Make	: AUDI A1 SPORTBACK	Policy No.	: 2070177852
Assignment Date	: 01/04/2022	Excess	: S\$0.00
Date of Inspection	: 31/03/2022	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,181.00
Revised Amount	:S\$	4,641.00
Check Items (Estimated)	:S\$	1,039.00
Total	:S\$	5,680.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 120,000.00
COE / PARF Rebate	:S\$ 54,688.00
Salvage Value	:S\$

Margin for Repair

:S\$ 65,312.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ASSIST TO AMEND THE ACCIDENT DATE TO 25/03/2022 INSTEAD OF 24/03/2022.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.