

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0245/2022/JT
DATE : 28-Mar-22
WIP : 17283

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days exclude 1 Sunday

Johnny Boo 5 Sept 22

OWNER'S NAME : MR CHEN JUNMING
ADDRESS : BLK 128 BEDOK NORTH ROAD ST 2
#05-08
SINGAPORE 460128
TELEPHONE : HP +65 98236541
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070177852-01
VEHICLE NO : **SMX 616 T**
MODEL CODE : AUDI A1 SB S LINE 1.0 TFSI
MODEL YEAR : 23/12/2020
ENGINE NO : DKJ 052759
CHASSIS NO : WAUZZZGB9LR044567
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Mar-22
PLACE OF ACCIDENT : 765A BEDOK RESERVOIR CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 616 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	
2	TO DISMANTLE AND RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 500.00
3	TO RESPRAY RHS REAR DOOR, RHS REAR FENDER AND RHS SILL PANEL TRIM.	\$ 3,000.00	\$ 1,100.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		\$ 5,922.00	\$ 1,600.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 616 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - RH	1	\$ 3,348.00	
2	REAR DOOR CATCH - RH	1	\$ 99.00	
3	REAR STONE CHIP GUARD - RH	1	\$ 493.00	
4	REAR WHEEL HOUSING LINER	1	\$ 198.00	
5	REAR ALUMINIUM RIM	1	\$ 1,076.00	
6	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 5,514.00	\$ -
TOTAL LABOUR CHARGES		:	\$ 5,922.00	\$ 1,600.00
GRAND TOTAL		:	\$ 11,436.00	\$ 1,600.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-27/05/22



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT