

Meng Yan (LKK Auto)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Thursday, 24 March, 2022 4:29 PM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: OD survey assignment for YQ1684J - DOA : 15/03/2022 Our Ref: NSV2200037/HLF

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	YQ 1684 J		
Policy Number	:	BVFCSE0013702102	Account Code:	B900SD0
Policy Excess	:	\$ 1,500	(Allied World waived \$) (Insured to pay \$)	
Voluntary Excess	:	\$	(No waiver)	
Sum Insured	:	Market Value with / without COE & PARF		
Make / Model	:	ISUZU NPR85UH5A 3.0 AMT MZ 300/C		
Name of Workshop	:	COMFORTDELGRO ENGINEERING PTE LTD		
Contact Number	:	6383 7441		
Person to Contact	:	MR PATRICK TIA		
Estimated Cost of repairs	:	\$ 2,850		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
(X)	Please revert with your preliminary survey report with photographs			

Regards,

Claims Division
