



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22003073/Gny3m4 Date: 30/09/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMR 4422R
	Policy No.	Z22VP05030760	Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/025617	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	04/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8X	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZGE206032763	Colour	WHITE
	Odometer	109703 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
	L/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/03/2022	Inspection Date	04/04/2022
	Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks				
	A)THE MARKET VALUE IS S\$70,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	