$51\,UBI\,AVE\,1,\#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK,SINGAPORE\,408933\,TEL:(065)\,62563561\,FAX:(065)\,62564315$ 

## **Immediate Advice**

To: AXA Insurance Pte Ltd DATE: 6/4/2022

## Survey details

Date of loss	1/4/2022
Date of appointment	4/4/2022
Date of survey	4/4/2022
Location of survey	SPEEDWERKZ PTE LTD

#### **Vehicle Details:**

Claim Type:	THIRD PARTY
Vehicle number	SLL 7988Z
Make and Model	MERCEDES BENZ B160
Date of registration	12/10/2011
Excess	
Market Value	\$64,000.00
Parf Rebate	\$38,336.00
Nett Loss	\$25,664.00

## Repair details

Initial Estimate

# Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	

Number of days of repair 6 days (est)

#### Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$5,000.00-\$6,000.00