## **Hsiao Tong (LKKAuto)**

From: Hsiao Tong (LKKAuto)

**Sent:** Monday, 15 May 2023 2:09 PM

To: MT\_Claim\_SG
Cc: Admin A

**Subject:** [SEEK MANDATE]- Your ref: 21/22/22/VC05/025633 // Our ref:

CC4/LPC22003084/Upa3q2[ACCIDENT INVOLVING GY6095Y(LONPAC) AND

GBA4653K(TP) ON 02/04/2022]

Attachments: LKK SURVEY REPORT & PHOTOS.pdf; LOD - GBA 4653K.pdf; TP SCENE PHOTOS.pdf

Your ref: **21/22/22/VC05/025633** Our ref: CC4/LPC22003084/Upa3q2

Dear Sirs/Mdm,

## ACCIDENT INVOLVING GY6095Y(LONPAC) AND GBA4653K(TP) ON 02/04/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "FASTECH AUTO PTE LTD" at \$8,099.50(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 7%GST)	\$ 22,788.43	\$ 7,757.50 (\$7,250.00 + 7%GST)
2. Loss of Rental (4days x \$85.00)	\$ 340.00	\$ 340.00 (4days x \$85.00)
3. LTA/ GIA SEARCH FEE	\$ 2.00	\$ 2.00
Total	\$ 23,130.43	\$ 8,099.50

Surveyor recommended 5days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 09/05/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25

S(408933)

