Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	
1)	: Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?	_		Transportation:
2)		Add Fee: : Site Insp (\$	)S + RS,SI
		: Interview (\$	) Photos

.ump Sum / I.B.I: (\$ ) TOTAL

## Alek certies

**FASTECH AUTO PTE LTD** 

3	TASTECT ACTO FIE EID	
8	1 Kaki Bukit Ave 6 #01-48 Autobay	1122
	Singapore 417883	126
		1200
	Tel No: 67452063/ 67467158 Fax No: 67458520	140
	Tax Reg No : 200006262D	1
	3	deys
	VEHICLE N. ODA ACEDIA	
	VEHICLE No: GBA 4653K	
1PC	REAR WINDSCREEN 17	\$1,499.80 🗙
1PC	REAR WIPER ARM	\$245.50 🗙
1PC	REAR WIPER ARM MOTOR	\$655.10 ×
1PC	REAR WIPER BLADE $\checkmark$	\$108.00
1PC	TAILGATE Sed 400	
		\$2,159.10
1PC	TAILGATE OUTER HANDLE SVE	\$455.80 🗶
1PC	TAILGATE INNER LOCK	\$425.80
1PC	TAILGATE INNER LOCK ACTUATOR Dye	\$455.20
1PC	TAILGATE LOCK STRIKER 11	\$45.00 ×
1PC	TAILGATE WEATHERSTRIP 7~1	\$399.80
2PCS	TAILGATE DAMPERS @\$366.10	\$732.20 ×
1PC	TAILGATE INNER TRIM BOARD 7010 399.10	\$455.10
1PC	TAILGATE REAR LOGO	
		\$85.00
1PC	DEAD DAY ADED A DAY OF A DAY OF A DAY AND A DA	\$681.10
4PCS	REAR BUMPER LOWER BRACKETS @\$35.00 Suf	\$140.00
2PCS	REAR BUMPER SIDE RETAINERS @\$105.00 C/ve	\$210.00
1PC	REAR END PANEL OUTER Bod (40) 725.10	\$981.10
1PC	REAR END PANEL INNER 3.5 PS	\$988.50
1PC	REAR END PANEL TOP STEEL PLATE	\$366.80 ×
2PCS	TAILLAMPS @\$455.10 CM 386.10 x 2 = 772.20	\$910.20
2PCS	TAILLAMP LOWER GARNISHS @\$165.00 Twl	\$330.00
2PCS	TAILLAMP HOUSING PANELS @\$688.50 N(SR v (S D)	\$1,377.00 1 0
1PC		AND COLUMN SERVICES
1PC	REAR SPARE TYRE BRACKET HOLDER	\$165.30 ×
1PC	REAR FENDER	\$1,971.10 ×
		\$16,297.60
	S.NETT	
1PC	REAR WINDSCREEN SEALANT	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	\$50.00 40
1PC	REAR LICENCE PLATE SUC	\$50.00 ×
1SET	REAR TAILGATE CORPORATE STICKER NO	\$500.00 🗶
1set		,
	TAILGATE 70km/h & 8 Pax STICKER	\$20.00
1SET	TAILGATE INNER TRIM BOARD CLIPS ALL	\$50.00 40
1SET	REAR BUMPER CLIPS	\$50.00 40
1SET	REAR BUMPER REVERSE SENSOR & hotel	\$280.00 200
1PC	REAR END PANEL SEALANT  NUL	\$50.00
	TO CHECK WIRING	\$50.00 20
	TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00
	TO DISMANTEL & REFEACED REVERSE SENSOR	300.00 7 0

TO DISMANTLE & REPLACED REAR WINDSCREEN TO TRANSFER TAILGATE MECHANISM TO DISMANTLE & REFIX REAR EXHAUST TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & REPLACED PARTS TO PUTTY & SPRAY PAINTING

\$150.00 / 20 \$100.00 60 11 \$100.00 X \$120.00 80 \$1,800.00 900 \$1,500.00 900 TOTAL \$21,297.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8731-50 252 P-6548-62 5.N-430 2-2130 2-2130 21262