

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliate data Factorial			-L'II- 000/A	01404040074
	AVA INCLIDANCE		n Internationale Des Experts En			
	AXA INSURANCE			Ref:	10/10/0001	010071/R1ty9
	8 SHENTON WAY AXA TOWERSING			Date:	10/10/2021	04/04/2022
				Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 6584B	Veh. Inspected	I	FBC 3822K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03K3B	Excess (\$)		0.00	
	Assign From	LOH Cynthia	Assign Date		10/10/2021	04/04/2022
<u>.</u>		Veh	icle Particulars & Conditi	on		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
			Conditions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
			Description of Damages			
•			General Information			
	Accident Date	14/10/2021	Inspection Dat	е	18/10/2021	
	Survey held at	RWAVE PTE LTD				
	50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578					
a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					