



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M03K3B

Date: 26th May 2022

Our Ref: CS3/ASM21010671/Rty3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBC 3822K

INSURED VEHICLE: SHD 6584B

ACCIDENT DATE: 14/10/2021

We thank you for your instruction on 04/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBC 3822K from M/s WG Appraisal Service.
- b) Singapore Accident Statement and Police Report of Vehicles FBC 3822K and SHD 6584B.
- c) Final Repair Bill of FBC 3822K from M/s Rwave Pte Ltd.
- d) Colour damaged vehicle photographs of FBC 3822K.

Pre-Repair Inspection Date : 18/10/2021 at M/s Rwave Pte Ltd, 50 Bukit Batok Street 23 #02-25 Midview Building, Singapore 659578.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBC 3822K
Make & Model	: Honda Wave 125X A
Year of Registration	: 2008
Chassis Number	: NF125ST0011790
Engine Capacity	: 125 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.