

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 06 Apr 2022

Preliminary Advice

Vehicle No	: SKZ788T	Accident Date	: 30/03/2022
Make	: CITROEN C4 PICASSO	Policy No.	: 80481271QMX
Assignment Date	: 05/04/2022	Excess	: S\$500.00
Date of Inspection	: 05/04/2022	Est. Duration of Repair	: 0
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	30,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	27,830.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,170.00

Remarks

- () The vehicle is economical for repair
- (X) The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.