



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

26/4/2022

To : AXA Insurance Pte Ltd

Survey details

Date of loss	3/4/2022
Date of appointment	5/4/2022
Date of survey	5/4/2022
Location of survey	T & S MOTOR SERVICE

Vehicle Details:

Claim Type:	TP
Vehicle number	SLJ 4063Y
Make and Model	TOYOTA SIENTA HYBIRD 1.5X A
Date of registration	8 Dec 2016
Excess	
Market Value	\$62,000
Salvage Value(est)	\$27,550
Nett Loss	\$34,450

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	7
--------------------------	---

Remarks:

Damage consistent
REPAIR RANGE 7000 - 8000

<u>Mandate</u>	%
	\$
	\$
	\$
Liability(TP)	\$
Proposed repair cost	\$
Loss of use	\$
Loss of rental	#VALUE!
Loss of income	
LTA search fees	
Others	
Total	

