




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS3/ASM22003123/Tty3e2 Date: 10/05/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 2663M	Veh. Inspected	SLJ 4063Y
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03XNU	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	05/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	NHP1707059929	Colour	SILVER
	Odometer	249578 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	6 mm
	L/H Front Tyre	185/60 R15	FIRENZA	6 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
	L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	03/04/2022	Inspect Date / Time	05/04/2022 (02:24 PM)
	Survey held at	T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days

Report Ref No. CS3/ASM22003123/Tty3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.