



# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

*Not Authorized  
Penney Blegging  
4 days*

## ESTIMATE

**WINNIE PANG SENG KHENG**

c/o 46 Lenton Plain

Singapore 786548

Date: 07/04/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA RAV 4 / SLX 4641 E</b>		
1 pc	front head lamp	2,967.10 X
1 pc	front bumper	1,363.23 ✓
1 pc	front bumper side retainer (LH)	86.70 ✓
1 pc	front bumper lower pad	477.30 ✓
1 pc	front fender (LH)	978.40 ✓
1 pc	front fender arch protector (LH)	294.70 ✓
1 pc	front knuckle arm	577.60 ?
1 pc	front lower arm	476.40 ?
1 pc	front steering tied rod	227.10 X
1 pc	front steering tied rod end	239.00 X
1 pc	front wheel bearing	341.50 ?
		<i>Sub-total</i> 5,061.93
		<i>Less 25%</i> 1,265.48
		<i>Sub-total</i> 3,796.45
1 pc	alloy rim <i>Pr?</i>	680.00 ✓
<div data-bbox="641 1066 1091 1432" data-label="Text" style="border: 1px solid black; padding: 5px;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>		
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		2,400.00 <i>400l</i>
To check wiring system.		50.00 <i>20l</i>
To spray painting on affected areas.		600.00 <i>400l</i>
To change alloy rim and balance wheel.		40.00 <i>20l</i>
To check wheel alignment.( 4 wheel)		85.00 <i>60l</i>
To replace undercarriage parts and machine press wheel bearing.		260.00 ?
<b>Total</b>		<b>7,911.45</b>