

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SJM 7680 D**
 Model : **Toyota Camry 2.0**
 Year : **2009**
 Chassis No : **MR053BK4107038318**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 1,128.00	\$ 1,128.00 481.25
2	Rear bumper bracket	2	\$ 49.80	\$ 99.60
3	Rear bumper reflector	2	\$ 118.60	\$ 237.20
4	Rear bumper reinforcement	1	\$ 531.50	\$ 531.50 337.10
5	Rear bumper inner sponge	1	\$ 240.00	\$ 240.00
6	Rear end panel	1	\$ 923.60	\$ 923.60
7	Rear end panel top garnish	1	\$ 357.40	\$ 357.40
Parts Sub Total :				\$ 818.25 3,517.30
Discount :				\$ 204.56 879.33
PARTS TOTAL :				\$ 613.69 2,637.98

CRAV
 NNX
 NDX
 BTU
 NSX
 NDX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00 30.00
3	Rear bumper side retainer	2	\$ 185.00 85.60	\$ 370.00 171.20
4	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00 200.00
5	Rear end panel sealant	1	\$ 100.00	\$ 100.00
6	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
SPECIAL NETT TOTAL :				\$ 401.20 1,070.00

NNX
 } NEG
 SC
 NNX

Nos.	LABOUR	S\$	
1	R&R rear bumper reverse sensors	\$ 60.00	100.00
2	Check wiring	\$	100.00
3	Upholstery	\$	300.00
4	Panel Beating	\$ 400.00	1,200.00
5	Rust proofing	\$	200.00
6	Spray Painting	\$ 200.00	1,200.00
LABOUR TOTAL :		\$ 660.00	3,100.00

NNX

NNX

Survey 6/4/2022 TGuin lin 1400 hrs
 Resurvey 7/4/2022 TGuin lin 1335 hrs

PARTS TOTAL : \$ 2,637.98
 SPECIAL NETT TOTAL : \$ 1,070.00
 LABOUR TOTAL : \$ 3,100.00
 GRAND TOTAL : \$ 6,807.98

Lump sum repair
 Repair days 4

Parts 613.69
 SN 401.20
 Labour 660.00
 1674.89
 @ 20% 334.98
 1339.91

LS \$ 1350/2

TGuin lin
 13/4/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: