



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLS1855B
Chassis No : JHMR1890HC203471
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : KOH THIEM TECK
Ins Policy No. :
Date of Accident : 30/3/2022

Document No. : SQT22000890
Date : 1. Apr 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72041114
Date | Time : 1. Apr 2022 12:08:11 PM

Page 1

LKK Auto Consultants hence notify the Repairer of the following:
Authorisation Date:

- To resurvey before/after spray painting
- To display (in) and part(s) during resurvey
- Parts to be subject to confirmation
- Third party survey Unit Price in Discrepancy Amount
- No illegal modification is allowed
- Supplementary claims must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

0% GST Amount
Amount incld GST

Item	Description	Qty	Unit Price	Disc/Adj	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KOH THIEM TECK OWNER INSURER: SINGAPORE LIFE LTD ACC DATE: 30/03/2022 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: XD3894L						
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR / BT / nbc	1	954.70 ✓	25	716.02	50.12	766.14
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER / nbc	1	40.90 ✓	25	30.67	2.15	32.82
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR / nbc	1	1067.00 ✓	25	800.25	56.02	856.27
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER / nbc	1	60.90 ✓	25	45.67	3.20	48.87
72450-T6A-003	MOLDING ASSYL.FR.DOOR / nbc	1	78.80 ✓	25	59.10	4.14	63.24
72950-T6A-003	MOLDING ASSYL.RR.DOOR / nbc	1	74.20 ✓	25	55.65	3.90	59.55
72181-T6A-J71	HANDLE COMPL.FR. / nbc	1	336.90 ✓	25	252.67	17.69	270.36
72183-SZW-J01	COVER COMPL.FR. / nbc	1	43.00 ✓	25	32.25	2.26	34.51
72681-SZW-J01	HANDLE COMPL.RR. / nbc	1	76.00 ✓	25	57.00	3.99	60.99
72683-SZW-J01	COVER COMPL.RR. / nbc	1	40.50 ✓	25	30.37	2.13	32.50
72682-T6A-A71	BASE COMPL.RR. ✓ BR	1	48.70 ✓	25	36.52	2.56	39.08
75332-T6A-J11ZG	GARNISH ASSYL.FR.DOOR LOWER / nbc	1	308.90 ✓	25	231.67	16.22	247.89
75333-T6A-J11ZD	GARNISH ASSYL.SLIDE DOOR LWR / nbc	1	290.10 ✓	25	217.57	15.23	232.80
			3420.6	Sum Item	2565.41	179.61	2,745.02
BOSUN	SUNDRIES	1	60.00 ✓	40 ✓	60.00	4.20	64.20
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	300.00 ✓	✓	300.00	21.00	321.00
BKDR31R	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR.	1	650.00 ✓	✓	650.00	45.50	695.50

Printed on 1/4/2022 1:19:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLS1855B
Chassis No : JHMRC1890HC203471
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : KOH THIEM TECK
Ins Policy No. :
Date of Accident : 30/3/2022

Document No. : SQT22000890 **Page** 2
Date : 1. Apr 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : K24W72041114
Date | Time : 1. Apr 2022 12:08:11 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOJSE	APPLY DOOR JOINT SEALANT.(NETT)	1	200.00	✓	200.00	14.00	214.00
BKCP11R	STRAIGHTEN & KNOCKOUT CTR PILLAR OUTER PANEL,	650 ₁	1500.00	1300 ✓	1500.00	105.00	1605.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1	1800.00	1080 ✓	1800.00	126.00	1926.00	
5740 Sum Labor					4510.00	315.70	4,825.70
3570							

Survey By Gino Qian
Date & Time 82880282 **Total Amount** 7,075.41 495.31 7,570.72
Excess Gino Qian @ Kkanto car **Total (Inclusive of GST)** 7,570.72
Status _____
Signature _____

11/4/22.
5 Pays
before paint photos.

3579.1
-25%: 2684.28
6254.28

Printed on 1/4/2022 1:19:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0028118 / LONPAC
Chassis No: JHMRC1890HC203471
License No: SLS1855B
Mileage: 97183
Engine No: K24W72041114

Document No: SVO22016939
Printed By: DESMOND TOH
Order Date: 11. April 2022
Order Time: 11:57:16 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 14540) OWNER: KOH THIEM TECK OWNER INSURER: SINGAPORE LIFE LTD ACC DATE: 30/03/2022 SURVEYED BY: GUO QIANG DATE: 11/04/2022 LKK REF: CC4/LPC22003153/pa3 TP INSURER: LONPAC TP VEH: XD3894L SUPPLEMENTARY PART						
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR	1	954.70	25	716.02	50.12	766.14
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER	1	40.90	25	30.67	2.15	32.82
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR	1	1,067.00	25	800.25	56.02	856.27
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER	1	60.90	25	45.67	3.20	48.87
72450-T6A-003	MOLDING ASSYL.FR.DOOR	1	78.80	25	59.10	4.14	63.24
72950-T6A-003	MOLDING ASSYL.RR.DOOR	1	74.20	25	55.65	3.90	59.55
72181-T6A-J71	HANDLE COMPL.FR.	1	336.90	25	252.67	17.69	270.36
72183-SZW-J01	COVER COMPL.FR.	1	43.00	25	32.25	2.26	34.51
72681-SZW-J01	HANDLE COMPL.RR.	1	76.00	25	57.00	3.99	60.99
72683-SZW-J01	COVER COMPL.RR.	1	40.50	25	30.37	2.13	32.50
72682-T6A-A71	BASE COMPL.RR.	1	48.70	25	36.52	2.56	39.08
75332-T6A-J11ZG	GARNISH ASSYL.FR.DOOR LOWER	1	308.90	25	231.67	16.22	247.89
75333-T6A-J11ZG	GARNISH ASSYL.SLIDE DOOR LWR	1	290.10	25	217.57	15.23	232.80
67365-T6A-J01	TAPE,L.FR.DOOR SASH UPPER ✓ NEC	1	39.70 ✓	25	29.77	2.08	31.85
72836-SHJ-A00	TAPESLIDE.DR.REFLECTOR. ✓ NEC	1	5.40 ✓	25	4.05	0.28	4.33
72965-T6A-003	MOLDINGL.SLIDE DOOR RETAINER ✓ NEC	1	103.00 ✓	25	77.25	5.41	82.66
72683-T6A-003	SEAT AL.RR. ✓ NEC	1	5.20 ✓	25	3.90	0.27	4.17
72684-T6A-003	SEAT BL.RR. ✓ NEC	1	5.20 ✓	25	3.90	0.27	4.17
		158.5	SUM PARTS:		2,684.28	187.92	2,872.20
BOSUN	1917 SUNDRIES	1	40.00		40.00	2.80	42.80
BKDR11R	1438 REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITES.(N)	1	300.00		300.00	21.00	321.00
BKDR31R	1438 REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATT. ITEM(N)	1	650.00		650.00	45.50	695.50
BOJSE	1917 APPLY DOOR JOINT SEALANT.(NETT)	1	200.00		200.00	14.00	214.00
BKCP11R	1729 STRAIGHTEN & KNOCKOUT CTR PILLAR OUTER PANEL, L/SIDE SILL PANEL AND REPLACE DAMAGED PARTS.	1	1,300.00		1,300.00	91.00	1,391.00
BP02R	1718	1	1,080.00		1,080.00	75.60	1,155.60



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0028118 / LONPAC	Document No:	SVO22016939
Chassis No:	JHMRC1890HC203471	Printed By:	DESMONDTOH
License No:	SLS1855B	Order Date:	11. April 2022
Mileage:	97183	Order Time:	11:57:16 AM
Engine No:	K24W72041114	Service Advisor:	IVAN TEO BOON KIAT

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.

SUM LABOUR:	3,570.00	249.90	3,819.90
TOTAL SGD	6,254.28	437.82	6,692.10

Total Payable (SGD) 6,692.10

GST Amount is calculated from individual line(s)