

Our Job Ref No : 305511402

Date : 11/04/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508909
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thovan

Vehicle Reg No. : SHB4803T

01/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ --- GBE5553M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$10,200.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thovan

Date : 22/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 05 Apr 2022)

Parts: 144 **TOYOTA PRIUS 1.5 HYBRID (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*REAR BUMPER	Cut	25.00	0.00	*503.04 FL
2	1		*REAR BUMPER CLIPS	nee	25.00	0.00	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Cut	25.00	0.00	*654.96 FL
4	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Cut	25.00	0.00	*654.96 FL
5	1		*COVER FLOOR UNDER NO. 2	mis	25.00	0.00	*220.50 FL
6	1		*REAR BUMPER UNDER SIDE COVER RH	Cut	25.00	0.00	*232.00 FL
7	1		*REAR BUMPER TOWING COVER	Cut	25.00	0.00	*82.70 FL
8	1		*REAR BUMPER SIDE RETAINER LH	nee	25.00	0.00	*112.70 FL
9	1		*REAR BUMPER SIDE RETAINER RH	nee	25.00	0.00	*112.70 FL
10	1		*REAR BUMPER REINFORCEMENT	PT	25.00	0.00	*378.32 FL
11	1		*REAR BUMPER ARM ASSY LH	DT	25.00	0.00	*139.60 FL
12	1		*REAR BUMPER ARM ASSY RH	DT	25.00	0.00	*139.60 FL
13	1		*REAR BUMPER SIDE EXTENTION RH	Cut	25.00	0.00	*148.40 FL
14	1		*REAR END PANEL	Svc X 7	25.00	0.00	*738.96 FL
15	1		*REAR END PANEL GARNISH	Svc X 7	25.00	0.00	*165.80 FL
16	1		*REAR WIRING ASSY	Svc X 7	25.00	0.00	*582.40 FL
17	1		*REAR SPOILER SUB ASSY	DT	25.00	0.00	*1,787.79 FL
18	1		*ROOF TOP CENTER COVER-BLACK	mis	25.00	0.00	*956.30 FL
19	1		*BACK DOOR GARNISH SUB ASSY	PT	25.00	0.00	*1,054.71 FL
20	1		*REAR TRUNK LID LOGO (PRIUS)	nee	25.00	0.00	*62.14 FL
21	1		*REAR TRUNK LID LOGO (HYBRID)	nee	25.00	0.00	*62.14 FL
22	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	nee	25.00	0.00	*81.43 FL
23	1		*TAIL LAMP UPPER RH	Cra	25.00	0.00	*557.90 FL
24	1		*TAIL LAMP LOWER RH	Cra	25.00	0.00	*570.00 FL
25	1		*REAR SPARE TYRE PANEL	xnn	25.00	0.00	*667.70 FL
26	1		*REAR WINDSCREEN GLASS WITH MOULDING	nee	25.00	0.00	*1,884.32 FL
27	1		*REAR TRUNK LID COVER	nee	25.00	0.00	*1,303.29 FL
28	1		*REAR TRUNK LID GLASS	nee	25.00	0.00	*1,569.70 FL
29	1		*REAR TRUNK LID HINGE LH	Svc nee X	25.00	0.00	*69.32 FL
30	1		*REAR TRUNK LID HINGE RH	Svc nee X	25.00	0.00	*69.32 FL
31	1		*REAR TRUNK LID LOCK	Svc jam	25.00	0.00	*530.79 FL
32	1		*REAR TRUNK LID COVER TRIM BOARD	Svc X 7	25.00	0.00	*254.40 FL
33	1		*BOOT LID TRIMBOARD CENTRE	Svc X 7	25.00	0.00	*159.60 FL
34	1		*BOOTLID TRIMBOARD SIDE RH	Svc X 7	25.00	0.00	*92.50 FL
35	1		*BOOT HANDLE	Svc X 7	25.00	0.00	*31.80 FL
36	1		*REAR TRUNK LID RUBBER	Svc X 7	25.00	0.00	*365.20 FL
37	1		*REAR TRUNK LID ABSORBER LH	Svc X 7	25.00	0.00	*287.50 FL
38	1		*REAR TRUNK LID ABSORBER RH	Svc X 7	25.00	0.00	*287.50 FL
39	1		*REAR TRUNK LID STOPPER LH	Svc X 7	25.00	0.00	*84.80 FL
40	1		*REAR TRUNK LID STOPPER RH	Svc X 7	25.00	0.00	*84.80 FL
41	1		*REAR EXHAUST PIPE CENTRE INSULATOR	X	25.00	0.00	*498.60 FL
42	1		*REAR EXHAUST PIPE HANGER	Svc X	25.00	0.00	*40.70 FL
43	1		*REAR EXHAUST PIPE	X	25.00	0.00	*1,163.40 FL
44	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO LH	ne	0.00	0.00	*100.00 F
45	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO RH	ne	0.00	0.00	*100.00 F

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
46	1		*REPLACE REAR BUMPER ADVERTISEMENT LOGO	NS /	0.00	0.00	*50.00 F
47	1		*REVERSE CAMERA ASSY	SVC X /	0.00	0.00	*380.00 F
48	1		*REAR TRUNK LID COMFORT & TEL NO. STICKER	NS /	0.00	0.00	*60.00 F
49	1		*REAR TRUNK LID APPS STICKER	NS /	0.00	0.00	*40.00 F
50	1		*REAR BUMPER RUBBER MAT	NS /	0.00	0.00	*55.00 F
51	1		*REAR REVERSE SENSOR	CUR /	0.00	0.00	*135.70 F

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	20,386.99
- List Item Discount on L Items (S\$)	4,866.57
Total Parts (S\$)	15,520.42

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 1,900.00
2	SPRAY PAINTING CHARGE	New	750 2000 1,350.00
3	TOWING FEE - KING DOLLY	New	100 150.00
4	CHECK ALL LIGHTING	New	40 80.00
5	TUFF KOTE	New	40 80.00
6	REMOVE/ REFIX EXHAUST PIPE	New	70 150.00
7	REMOVE/ REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
8	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (\$\$)			3,890.00

ComfortDelGro Engineering Pte Ltd/SHB4803T/05/04/2022 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thavan

82235769

6/4/22 1645

LPS repair

4 days w/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: