



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS/III22003168/Kvy3	
			Date: 06/04/2022	
			Code: III2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SFH 8800S	
	Policy No. D20MFL0000326_01	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From Gabriel Wee	Assign Date	06/04/2022	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 25/03/2022	Inspection Date	06/04/2022	
	Survey held at 205 Braddell Road, 579701 Toa Payoh			
	Repairer COMFORTDELGRO ENGINEERING PTE LTD			
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			