



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS/AIS22003179/Rqy3e2

Date: 30/05/2022

Code: AIS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBL 748P	Veh. Inspected	SHF 365X
Policy No.		Coverage (\$)	0.00
Claim No.	2022 22004418SL	Excess (\$)	0.00
Assign From	SHANTI	Assign Date	06/04/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803578442	Colour	MAROON
Odometer	517723 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	6 mm
L/H Front Tyre	195/65 R15	SAILUN	6 mm
R/H Rear Tyre	195/65 R15	SAILUN	6 mm
L/H Rear Tyre	195/65 R15	SAILUN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/04/2022	Inspection Date	06/04/2022
Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------