

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305511409
Date : 07.04.22

Fax :

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHD6507A

Date of Accident : 04.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SKZ1611M
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges (include advertisement stickers etc, if any)
- Total for Part-By-Part Repair Cost**
- (c.) Lumpsum Repair (if applicable) \$2,050.00
Total for Lumpsum repair cost after Less: 20% \$2,050.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : LIM TS
Name : LIM TS
Tel : 62148398
Fax : 65468156

Signature : [Signature]
Name : THEVAN
Date : 21/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

(08/11/13)

ASS. REC. BY:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

SAS - KLV

LKK -

From: _____

DATE: **05.04.22**

Estimated Cost

MODEL: **Toyota Prius**

OD / TP / WS

INSURANCE: **NTUC CLS**

To Inspect Vehicle

VEHICLE NO.: **SHD6507A**

MVA: **LIMITS**

at Workshop

of _____

Insured:

Policy No.

Claims No.

Sum Insured

(Client's)

Make of

(Policy)

Remarks

Balance

IDAC

GIA

Est.

Lun

CA

D:

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk Outer Garnish	1		
	Rear Trunk Lid Logo (Prius)	1		\$1,054.71
	Rear Trunk Lid Logo (Hybrid)	1		\$62.14
	Rear Trunk Lid Logo (Toyota Star)	1		\$62.14
	Rear Bumper - G4A	1		\$81.43
	Rear Bumper Re-Inforcement	1		\$551.89
	Rear Bumper Lower Cover-Black	1		\$378.32
	Rear Bumper Clips	10	\$2.20	\$654.96
				\$22.00
	SUB TOTAL			\$2,867.59
	LESS 25%			\$716.89
	DISCOUNTED TOTAL			\$2,150.69
	Reverse Sensor	1		\$135.70
	Rear Trunk ComfortDelGro	1		\$30.00
	Rear Trunk 65521111	1		\$30.00
	Rear Trunk APPS	1		\$40.00
	SUB NETT TOTAL			\$235.70
	LESS 10%			\$23.57
	NETT TOTAL			\$212.13
	TOTAL SPARE PARTS			\$2,362.82
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$40.00
	Tuff Kote			\$40.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$1,600.00
	ESTIMATE TOTAL			\$3,962.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan

82235769

5/4/22 1615

4/5 repair

3elaysw