

DETAILS

Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2022)
 143 MERCEDES-BENZ E200 AVG 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SMH678Z)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1			*1 pc front bumper	my CM	0.00	0.00 ✓ *760.00
1			*1 pc front bumper LH side garnish	CM	0.00	0.00 ✓ *55.00
1			*2 pcs front bumper LH outer parking sensors @ \$110/pc	su	0.00	0.00 X *220.00
1			*1 pc front bumper LH side retainer	12 DIT	0.00	0.00 ✓ *18.00
1			*1 pc front bumper LH inner frame	CM	0.00	0.00 ✓ *50.00
1			*12 pcs front bumper rivets @ \$5/pc	my	0.00	0.00 ✓ *60.00
1			*1 pc front LH fender	R	0.00	0.00 X *590.00
1			*1 pc LH headlamp	my CM	0.00	0.00 ✓ *1,800.00
Total Parts (S\$)						3,553.00

*Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

on Miscellaneous Items
no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amot
Labour Items			
	Remove & refix front bumper & attachments, grille, headlamp, frt LH fender & realign the same	New	400/ 500
	Putty & respray frt bumper & parking sensors, frt LH fender & all affected areas	New	400/ 500
	Remove & refix frt LH rim, respray & realign the same	New	60/ 100
	To conduct computerised wheel alignment	New	✓ 60
	Rustproofing	NA New	X 30
Gross Labour Cost (\$)			1,190.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**
< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: