



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2202540

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 05/05/2022
Reference CS3/III22003212/Vvy3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 4899R
Insured Veh. SLU 5410P
Claim No. MFL2022D0001848
Policy No. D21MFL0005172
Accident Date 06/04/2022
Inspection Date 07/04/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 07.04.2022 05.00pm	
- Dismantle Inspection 08.04.2022 04.26pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM