

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Apr 2022 19:37	<b>CIm Veh Model Changed</b>		[ ] Merimen Administrator
2	01 Apr 2022 19:37	<b>CIm Created</b>	Reg No: SLF5683Y. Policy No: 2100480662-05. Acct Date: 2022/04/01. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SPOR22410003	[I] Merimen Administrator
3	07 Apr 2022 12:27	<b>CIm Registration Modified</b>	Setl.Type:3->0. Claim Type:SC->OD.	[ ] CELINE FONG
4	07 Apr 2022 12:27	<b>Adj CIm Retrieved</b>	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] CELINE FONG
5	07 Apr 2022 12:27	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	07 Apr 2022 12:27	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2022/04/19	[A] CELINE FONG
7	07 Apr 2022 12:27	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	07 Apr 2022 12:27	<b>CIm Registration Modified</b>	Rep:1137->200611.	[A] CELINE FONG
9	07 Apr 2022 12:27	<b>CIm Veh Model Changed</b>	(204926) AUDI Q7 2.0 TFSI QU (A).	[A] CELINE FONG
10	07 Apr 2022 12:27	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] CELINE FONG
11	07 Apr 2022 14:54	<b>Adj Rpt Initiated</b>		[A] Elaine Kuan Hwa Meen
12	07 Apr 2022 14:54	<b>CIm Dtl Modified</b>	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	07 Apr 2022 14:54	<b>CIm Dtl Modified</b>	JPJ Reg. Date: -> 2016/08/30.	[A] Elaine Kuan Hwa Meen
14	07 Apr 2022 14:54	<b>CIm Details Notified</b>		[A] Elaine Kuan Hwa Meen
15	07 Apr 2022 15:24	<b>CIm Registration Modified</b>	Init.Est.:->5,000 - 6,000. Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
16	07 Apr 2022 15:32	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2022/04/19	[A] DENISE TAY KWEE CHENG
17	08 Apr 2022 08:02	<b>Adj Mandate Request</b>	Cur.Req:47156.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
18	08 Apr 2022 14:42	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2022/04/19. Mandate Remarks: Vehicle may commence repair - Rear Left Rim not consistent, to remove with alignment labour #14 - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and co	[I] Lim, Kok-Chong
19	08 Apr 2022 14:42	<b>Adj Mandate Set</b>	Approved:44610.00:Vehicle may commence repair - Rear Left Rim not consistent, to remove with alignment labour #14 - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint phot	[I] Lim, Kok-Chong
20	08 Apr 2022 14:57	<b>Adj Next Rpt Changed</b>	Cur Rpt:Final Rpt. Cur Due Date:2022/04/19. Mandate Remarks: Vehicle may commence repair - Rear Left Rim not consistent, to remove with alignment labour #14, Rear Left Door and Left Side Skirt labour & spray paint - refer Adrian Checked and Supple	[I] Lim, Kok-Chong
21	08 Apr 2022 14:58	<b>Adj Mandate Set</b>	Approved:44610.00:Vehicle may commence repair - Rear Left Rim not consistent, to remove with alignment labour #14, Rear Left Door and Left Side Skirt labour & spray paint - refer Adrian Checked and Supplementary items to resurvey with CLEAR p	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

### ACTIVITY

No record

**Merimen Billing for this case - Transaction History**

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2781371	07 Apr 2022 14:54:43	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLF5683Y		11.00