

Borneo Motors

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #07-03 Singapore 138498
	Document Date 05/04/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	24/10/2017	SLT2545J	0	14379	66TP/SLT2545J/050422

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBK3FUX03574487	2ZRS105306	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PZ5551S ACC DATE:05/04/22 DRIVE IN:05/04/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 ✓ 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				✓ 180.00
3	B	BP-LAB2 R/I INTERIOR UPHOLSTERY TO FAC REPAIR				✓ 720.00
4	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL 720 STRAIGHTEN AND REALIGN ACC AFF AREA				3600 ✓ 4320.00
5	B	BP-RES2 RESRPAY ACC AFF AREA 500				3245 ✓ 3540.00
6	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				✓ 180.00
7	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				✓ 180.00
8	1	T08826-08115 PANEL BONDING AD	1.00	267.20		✓ 267.20
9	2	U52159-47913 COVER, RR BUMPER	1.00	469.50		✓ 469.50
10	3	U52575-47040 RETAINER, RR BUMPER	1.00	124.90		✓ 124.90
11	4	U52565-47900 FILLER, RR BUMPER	1.00	131.10		✓ 131.10
12	5	U61601-47150 PANEL SUB-ASSY,	1.00	925.90		✓ 925.90
13	6	U58745-47030 PROTECTOR, QUARTER	1.00	24.40		✓ 24.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			11,163.00
Tan Jia 97495749 up 21/4/22 @ 2:15 pm Repair before paint Tan Jia 97495749	Please acknowledge receipt of vehicle	Parts 1,943.00 Labour 9,040.00 Sublet 180.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 781.41 Less 0.00 Amount Due 11,944.41

Company Copy

Labour - 8155
Parts - 1657
97842 # 10 days #