

### SERVICE ESTIMATE

##### - C00001 SL: SERVICE SALES - PC

Mr Nick Lim  
#02-04 Lorong H Telok Kurau  
The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
Svc Consultant :  
Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X  
Inv.No. . : B&P 0 Page 1  
Inv.date. : 06/04/2022  
WIP No. . : 20069  
Veh.In/Out:  
\*Tel.No. . : Mobile: 98472080  
Reg.No. . : SMX3417G  
Reg.date . : 16/01/2020  
Mileage .. : 0  
Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRT BUMPER, RADIATOR GRILLE, LOGO, HEADLAMP LH/RH, LOWER MESH GRILLE, SPOILER, ETC	550 0	1650.00	0	1100	1,650.00	S
800	TO SPRAY BONNET, FRT BUMPER, REINFORCEMENT, ETC	500 0	2000.00	0	1000	2,000.00	S
802	TO REPLACE FRONT SUPPORT PANEL ETC	0	2200.00	0	1650	2,200.00	S
802	TO VACUUM & TOP UP AIRCON GAS	0	600.00	0	✓	600.00	S
287	TO REMOVE & REPLACE DASHBOARD, AIRBAG COMPONENTS, ETC	150 0	4800.00	0	2400	4,800.00	S
287	TO REPLACE SEAT BELT & SEAT BE BUCKLE FRONT & REAR.	0	3600.00	0	1800	3,600.00	S
287	TO RESET AIRBAG MODULE SYSTEM	0	1200.00	0	600	1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0	✓	450.00	S

*Taufik 97495749 / 62563561*  
*Not Au thovise, Resurvey*  
*7/4/22 345*  
*Excuse: to be advise*  
*Resurvey before paint.*  
*14 days.*  
*To check repair limit*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
#02-04 Lorong H Telok Kurau  
The Bale

Singapore 425991

GST Reg.No:M28920628X  
Inv.No. . : B&P      0    Page 2  
Inv.date. : 06/04/2022  
WIP No. . : 20069  
Veh.In/Out:  
\*Tel.No. . : Mobile: 98472080  
Reg.No. . : SMX3417G  
Reg.date . : 16/01/2020  
Mileage .. : 0  
Chassis No: VF1RFA00963212476

Closed by .... : Juan Paulo Bongon Ba  
Svc Consultant :  
Remarks ..... : Mr Nick Lim

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
R06	NUMBER PLATE & HOLDER	0	60.00	0	X	60.00	S
	BUMPER FRT GS4	1.0 EA	1457.30		de/	1,457.30	S
	BUMPER FRT TOW COVER	1.0 EA	117.00		X	117.00	S
	BUMPER FRT SUPPORT B	1.0 EA	132.90		?	132.90	S
	BUMPER UNDER COVER F	1.0 EA	617.80		?	617.80	S
	CONVERGENT AIR GUIGE	1.0 EA	300.90		?	300.90	S
	FOG LAMP FRT INNER B	1.0 EA	197.90		X	197.90	S
	BUMPER LOWER FRT GS4	1.0 EA	473.80		?	473.80	S
	BUMPER FRT CENTER IN	1.0 EA	239.10		?	239.10	S
	BUMPER FRT TOP INNER	1.0 EA	458.40		?	458.40	S
	FOG LAMP MOULDING OU	1.0 EA	261.40		de/	261.40	S
	FOG LAMP COVER CHORM	1.0 EA	261.40		cut/	261.40	S
	SUPPORT BRACKET, HEA	2.0 EA	125.60		?	251.20	S
	SUPPORT BRACKET, HEA	1.0 EA	125.60		?	125.60	S
	BUMPER MOUDLING CLIP	10.0 EA	4.00		nee/	40.00	S
	BUMPER BRACKET FRT R	1.0 EA	154.60		de/	154.60	S
	BUMPER BRACKET FRT L	1.0 EA	154.60		de/	154.60	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
#02-04 Lorong H Telok Kurau  
The Bale

Singapore 425991

GST Reg.No:M28920628X  
Inv.No. . : B&P      0    Page 3  
Inv.date. : 06/04/2022  
WIP No. . : 20069  
Veh.In/Out:  
\*Tel.No. . : Mobile: 98472080  
Reg.No. . : SMX3417G  
Reg.date . : 16/01/2020  
Mileage .. : 0  
Chassis No: VF1RFA00963212476

Closed by .... : Juan Paulo Bongon Ba  
Svc Consultant :  
Remarks ..... : Mr Nick Lim

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	AIR INTAKE HOSE, BUM	1.0 EA	139.40		?	139.40	S
	AIR INTAKE GUIDE FRT	1.0 EA	165.30		?	165.30	S
	AIR FLAP GUIDE LOWER	1.0 EA	251.60		?	251.60	S
	BUMPER FRT TOP GRILL	1.0 EA	473.80		cut	473.80	S
	GRILLA LINING PANEL	1.0 EA	346.80		?	346.80	S
	GRILLA TOP CHROMA ST	1.0 EA	231.60		? <del>req</del>	231.60	S
	MLDG-GRILLE RAD, S4	1.0 EA	317.80		?	317.80	S
	LOGO FRT GRILLE GS4	1.0 EA	167.00		cut	167.00	S
	STICKER M4S	1.0 EA	17.50		req	17.50	S
	LABEL TOP PANEL M4H	1.0 EA	8.80		req	8.80	S
	LABEL-DIESEL EXH EMI	1.0 EA	8.80		req	8.80	S
	WHEEL ARCH - FRT LH	1.0 EA	294.60		X	294.60	S
	WHEEL ARCH - FRT RH	1.0 EA	294.60		X	294.60	S
	WHEEL ARCH CLIP J5AL	20.0 EA	6.00		req	120.00	S
	BONNET FRT GS4	1.0 EA	1348.00		b6	1,348.00	S
	BONNET INSULATE GS4	1.0 EA	315.70		X	315.70	S
	BONNET HINGE LH GS4	1.0 EA	134.30		?	134.30	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 4  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage ... : 0  
 Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BONNET HINGE RH GS4	1.0 EA	134.30		?	134.30	S
	BONNET DAMPER L&R GS	2.0 EA	120.20		X	240.40	S
	BONNET LOCK GS4	1.0 EA	191.10		?	191.10	S
	BUMPER FRT REINFORCE	1.0 EA	744.40		?	744.40	S
	LOWER RADIATOR PANEL	1.0 EA	569.50		?	569.50	S
	GRILLA PANEL INNER A	1.0 EA	1214.30		? 1	214.30	S
	GRILLA PANEL INNER L	1.0 EA	92.10		?	92.10	S
	GRILLA PANEL INNER L	1.0 EA	93.10		?	93.10	S
	COOLANT 5 LTR	2.0 EA	24.20		24.1	48.40	S
	GRILLA PANEL INNER T	2.0 EA	116.20		?	232.40	S
	BRACKET, FENDER FRT	1.0 EA	247.30		?	247.30	S
	BRACKET, FENDER FRT	1.0 EA	261.20		?	261.20	S
	FENDER BRACKET FRT L	1.0 EA	130.00		?	130.00	S
	BRACKET, FENDER FRT	1.0 EA	130.00		?	130.00	S
	RADIATOR AIR GUIDE F	1.0 EA	112.00		?	112.00	S
	AIR COOLER GUIDE AIR	1.0 EA	46.60		?	46.60	S
	FAN MOTOR GS4M4RS	1.0 EA	937.20		?	937.20	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim  
 #02-04 Lorong H Telok Kurau  
 The Bale

Singapore 425991

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 5  
 Inv.date. . : 06/04/2022  
 WIP No. . . : 20069  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98472080  
 Reg.No. . . : SMX3417G  
 Reg.date . . : 16/01/2020  
 Mileage . . : 0  
 Chassis No: VF1RFA00963212476

Closed by . . . . : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks . . . . . : Mr Nick Lim

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	AIR INTAKE FLAP GUID	1.0 EA	597.40		?	597.40	S
	A/C CONDENSER GS4 M4	1.0 EA	930.00		?	930.00	S
	RADIATOR S4 M4S GS4	1.0 EA	725.40		?	725.40	S
	AIR COOLER ASSY- GS4	1.0 EA	898.10		?	898.10	S
	HEADLAMP RH (Privile	1.0 EA	1877.70		?	1,877.70	S
	HEADLAMP LH (Privile	1.0 EA	1877.70		?	1,877.70	S
	FOG LAMP-RH FRT CAP	1.0 EA	248.10		X	248.10	S
	FOG LAMP-LH FRT CAP	1.0 EA	248.10		X	248.10	S
	BUMPER HARNESS- FRT	1.0 EA	198.40		?	198.40	S
	PARK SENSOR BOTH CTR	4.0 EA	557.20		?	2,228.80	S
	BLIND SPOT SENSOR GS	2.0 EA	361.70		?	723.40	S
	DASHBOARD	1.0 EA	3674.90		act	3,674.90	S
	DASHBOARD COVER GS4	1.0 EA	1025.70		de	1,025.70	S
	*E* PASSENGER AIR BA	1.0 EA	1211.00		act	1,211.00	S
	*E* SEAT BELT FRT LH	1.0 EA	743.40		act	743.40	S
	*E* SEAT BELT FRT RH	1.0 EA	743.40		act	743.40	S
	*E* SEAT BELT TENSIO	1.0 EA	210.90		act	210.90	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mr Nick Lim

#02-04 Lorong H Telok Kurau  
The Bale

Singapore 425991

Closed by .... : Juan Paulo Bongon Ba  
Svc Consultant :  
Remarks ..... : Mr Nick Lim

GST Reg.No:M28920628X

Inv.No. . : B&P                      0    Page 6  
Inv.date. : 06/04/2022  
WIP No. . : 20069  
Veh.In/Out:  
\*Tel.No. . : Mobile: 98472080  
Reg.No. . : SMX3417G  
Reg.date . : 16/01/2020  
Mileage .. : 0  
Chassis No: VF1RFA00963212476

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	*E* SEAT BELT TENSIO	1.0 EA	210.90		act	210.90	S
	SEAT BELT BUCKLE FRT	1.0 EA	263.50		act	263.50	S
	SEAT BELT BUCKLE FRT	1.0 EA	263.50		act	263.50	S
	*E* BELT-2ND ROW RH	1.0 EA	743.40		act	743.40	S
	BELT-2ND ROW LH	1.0 EA	963.30		act	963.30	S
	BELT-2ND ROW CTR	1.0 EA	963.30		act	963.30	S
	AIRBAG COMPUTER GS4	1.0 EA	1356.90		act	1,356.90	S
	*E* STEERING WHEEL A	1.0 EA	1148.80		act	1,148.80	S
	ROTARY SWITCH GS4 KJ	1.0 EA	429.90		act	429.90	S

Gross Total.                      56,369.70

**Labour Total**                      16,560.00  
**Parts Total**                        39,809.70  
**Package Total**                      0.00

Net.....                            56,369.70  
GST @ 7.0%                        3,945.88  
Total.....                          60,315.60  
Paid.....                            0.00  
Please Pay..                        60,315.60

GST: S=StdRated; O=OutOfScope; Z=ZeroRated