

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 20 Apr 2022

Preliminary Advice

Vehicle No : SMX3417G Accident Date : 01/04/2022
Make : RENAULT SCENIC Policy No. :
DMPCSNW00130222100
Assignment Date : 07/04/2022 Excess : S\$0.00
Date of Inspection : 07/04/2022 Est. Duration of Repair : 14
Inspection At : WEARNES AUTOMOTIVE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 60,057.90	(Estimate \$56,369.70 + Supplementary \$3,688.20)
Revised Amount	:S\$ 32,934.90	(Inclusive of supplementary)
Check Items (Estimated)	:S\$ 17,501.00	
Total	:S\$ 50,435.90	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value	:S\$ 105,000.00
COE / PARF Rebate	:S\$ 40,019.00
Salvage Value	:S\$
Margin for Repair	:S\$ 64,981.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.