



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003230/Evy3n2	
			Date: 31/05/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4753Z	Veh. Inspected	SKA 8T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/22/2018	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	07/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	BMW IX3	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	WBY42DU050S260197	Colour	WHITE
	Odometer	4868 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R20	BRIDGESTONE	4 mm
	L/H Front Tyre	245/45 R20	BRIDGESTONE	4 mm
	R/H Rear Tyre	245/45 R20	BRIDGESTONE	4 mm
	L/H Rear Tyre	245/45 R20	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/04/2022	Inspection Date	09/05/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	