



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI22003234/y3 Date: 07/04/2022 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	QX 1589J
	Policy No.	DMCVSNW00138992101	Coverage (\$)	0.00
	Claim No.	SNM22D201968/C01/TANKL	Excess (\$)	0.00
	Assign From	TAN KAH LEONG	Assign Date	07/04/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	21/03/2022	Inspection Date	08/04/2022
	Survey held at	10 DEFU LANE 8		
	Repairer	INDECO ENGINEERS PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			