



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003241/Kvy3e2 Date: 30/05/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 853U		Veh. Inspected	SLN 7701Z
Policy No.			Coverage (\$)	0.00
Claim No.	MLPAISCL2022-00040FR		Excess (\$)	0.00
Assign From	SHANTI		Assign Date	07/04/2022
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	MR053REH104559109		Colour	METALLIC BLACK
Odometer	172003 KM		Steering	JAMMED
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45Z R17	KUMHO	8 mm	
L/H Front Tyre	215/45Z R17	KUMHO	8 mm	
R/H Rear Tyre	215/45Z R17	PETLAS	9 mm	
L/H Rear Tyre	215/45Z R17	PETLAS	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/04/2022		Inspection Date	08/04/2022
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	