

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

SUPPLEMENTARY

EST. No: EST0029129
Tang Sow Boon

Page: 1 of 1
Your ref.: TP-XE 853U Allianz
Job No.: 72564
Our ref: 22.04.03
Payment
Date: 18/4/2022

Attn

Vehicle No: SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ...: 2/4/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
SUPPLEMENTARY ITEM:					
1.00	Pc	Rear fender RH bent	939.20	25.00	704.40
1.00	Pc	Front tie rod end RH bent	140.10	25.00	105.08
Labour & Misc:					
1.00		To remove + refix rear windscreen	140.00		140.00 120
1.00		To supply sealant	40.00		40.00 40
1.00		To dismantle + refix rear passenger seat, carpet, etc	120.00		120.00 100
Sub-Total					1,109.48
GST 7.00%					77.66
Total					S\$ 1,187.14

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."