

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	Ref:		CS3/LPC22003268/Rqy3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	28/04/2022	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 9366E	Veh. Inspected		SJD 7667R
	Policy No.	cy No. Coverage (\$)			0.00
	Claim No.	21/22/22/VC00/025627	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		08/04/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC 1.5 TURBO SR	c.c		1498
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	MRHFC1660GT000038	Colour		BLUE
	Odometer	132400 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	235/40Z R18	PIRELLI		6 mm
	L/H Front Tyre	235/40Z R18	PIRELLI		6 mm
	R/H Rear Tyre	235/40Z R18	PIRELLI		6 mm
	L/H Rear Tyre	235/40Z R18	PIRELLI		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S FRONT PORTION.			
5.	General Information				
	Accident Date	04/04/2022	Inspect Date /	Time	08/04/2022 (04:00 PM)
	Survey held at	1007 BUKIT MERAH #01-09			
	Repairer	ZOLAR AUTO SERVICES			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22003268/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser