

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: MPC21D00002201 Date: 20th April 2022

Our Ref: CS1/ICS22003270/Eqy3q2

M/s ECICS Ltd

10 Eunos Road 8 Singapore Post Centre #09-04A Singapore 408600 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJX 1771G INSURED VEHICLE: SJR 7129D ACCIDENT DATE: 12/12/2021

We thank you for your instruction on 08/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJX 1771G from M/s Precision Appraisal Services.
- b) Survey report by Precision Appraisal Services with colour photographs.
- c) Final Repair Bill of SJX 1771G from M/s New Pioneer Auto Pte Ltd.
- d) Singapore Accident Statement of Vehicles SJX 1771G and SJR 7129D.
- e) Colour damaged vehicle photographs of SJX 1771G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJX 1771G

Make & Model : Mercedes Benz C200 CGI AMG

Year of Registration : 2017

Chassis Number : WDD2050422R178395

Engine Capacity : 1991 cc

- 2. We recommend that the repairs of the entire damage require about 35 (Thirty-Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.