

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM WEISHAN REAGAN
BLK 52 ANCHORVALE CRESCENT
#13-12
SINGAPORE 544630

Estimate No: MC1902587
Date: 07 Apr 2022
Policy No: MT/00744740/02
Veh Reg No: SKX7480U
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 06/04/2022
TP Veh Reg No: GBH5885P

Estimate Repair Cost to Vehicle No :SKX7480U

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT FENDER LH	1 PC	300.70	
2 FRONT FENDER LOWER GARNISH LH	1 PC	0.00	
3 FRONT FENDER BRACKET REAR LH	1 PC	18.90	
4 FRONT FENDER COWLING LH	1 PC	96.30	
5 FRONT FENDER COWLING CLIPS	8 PC	42.40	
6 FRONT DOOR LH	1 PC	720.40	
7 FRONT DOOR TAPE FRONT LH	1 PC	8.30	
8 FRONT DOOR TAPE TOP LH	1 PC	24.30	
9 FRONT DOOR TAPE REAR LH	1 PC	24.90	
10 FRONT DOOR LOWER GARNISH WITH GARNISH CHROME MOULDING LH	1 PC	290.70	
11 FRONT DOOR RUBBER @DOOR LH	1 PC	94.20	
12 FRONT DOOR RUBBER @DOOR BOTTOM LH	1 PC	19.40	
13 FRONT DOOR HINGE LOWER LH	1 PC	48.10	
14 FRONT DOOR CHECK LH	1 PC	60.50	
15 FRONT DOOR WINDOW REGULATOR WITH MOTOR LH	1 PC	300.20	
16 FRONT DOOR LOCK LH	1 PC	280.40	
17 FRONT WHEEL HUB WITH BEARING LH	1 PC	240.70	
		2,570.40	
	Less 20%	514.08	2,056.32
Special Nett			
18 TYRE LHF -check price	1 PC	0.0000	
19 SPORT RIM LHF -check price	1 PC	0.0000	
		0.00	0.00
LABOUR			
20 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
21 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	
22 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
23 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT FENDER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
24 TO SPRAY FRONT FENDER LH, FRONT DOOR LH	1 PC	500.00	
		1,360.00	1,360.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM WEISHAN REAGAN
BLK 52 ANCHORVALE CRESCENT
#13-12
SINGAPORE 544630

ATTN:

Estimate No: MC1902587
Date: 07 Apr 2022
Policy No: MT/00744740/02
Veh Reg No: SKX7480U
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Your Ref No: -
Claim Type: Third Party
Accident Date: 06/04/2022
TP Veh Reg No: GBH5885P

Estimate Repair Cost to Vehicle No :SKX7480U

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 3,416.32
Add GST @ 7%			239.14
Total Amount Payable			S\$ 3,655.46

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SIX HUNDRED FIFTY FIVE AND CENTS FORTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORIZED SIGNATURE