



ZOOM AUTOWERKS PTE LTD

LKK Auto Consultants hereby certify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during repair
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed
is subject to final approval from Insurance Company

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

18 April 2022

Acknowledged by Repairer

Signature:

Date:

Not Authorized

1/5 \$4500
11/4/22

5 days

NO.: SLQ 7552 X
MAKE/MODEL: TOYOTA WISH

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$S)
LIST ITEMS		
1	Rear windscreen moulding	165.58
1	Rear tailgate	1,466.25
2	Rear tailgate dampers	423.00
1	Rear tailgate inner trim board	485.50
2	Rear tailgate lamps	465.80
1	Rear tailgate lock	350.96
1	Rear tailgate logo	68.50
1	Rear tailgate rubber	370.50
1	Rear tailgate "VALVE MATIC" emblem	72.00
2	Rear taillamps	881.00
1	Rear end panel	596.50
1	Rear end panel inner trim garnish	253.20
1	Rear bumper	991.76
1	Rear bumper bracket	68.50
1	Rear bumper reflector	86.95
2	Rear bumper side retainers	128.86
1	Rear fender -LH	1,013.50
1	Rear floor board	426.50
		8,314.86
Less 25%		2,078.72
		6,236.15

SPECIAL NETT ITEMS

1	Rear windscreen sealant	80.00
1	Rear bumper clip (1 set)	60.00
1	Rear reverse sensor (1 set)	350.00
		490.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	80.00
2	To remove and refit inner garnishes.	150.00
3	To remove and refit rear reverse sensor.	150.00
4	To transfer rear tailgate mechanism and wiring assembly.	80.00
5	To remove and refit rear windscreen glass.	180.00
6	To apply undercoating.	200.00
7	Panel beating.	1,500.00
8	To re-spray painting on the affected areas.	1,400.00
		3,740.00

GRAND TOTAL :

P. 4596.87

25%

3446.90

290

1890

5626.90 4501

\$ 10,466.15