




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHOR SAW THENG			Ref: CS3/ASM22003310/Rny3e2 Date: 18/01/2023 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHB 6359X	Veh. Inspected	SJX 8344K	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M03Y7R	Excess (\$)	0.00	
Assign From	KHOR SAW THENG	Assign Date	11/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CRV 2.4 S/R	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHRM3850HP000024	Colour	BLACK	
Odometer	132350 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	MICHELIN	6 mm	
L/H Front Tyre	225/60 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/60 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/60 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	07/04/2022	Inspect Date / Time	12/04/2022 (11:18 AM)	
Survey held at	HONG SAN HONG WEI PTE LTD 1002 BUKIT MERAH LANE 3 #01-85 ALEXANDRA VILLAGE IND'L EST SINGAPORE 159719			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/ASM22003310/Rny3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.