

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: NISSAN ALMERA

Engine/Chassis No.: MNTBBAN17Z0004073


Date of accident:

Damaged area: O/S

Date: 13/04/2022

Claim Type: TP

VRN: SKM7818M



Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	3	\$ 600.00
2	Supply spray paint material and necessary items to respray affected area / panel.	3	\$ 600.00
3	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 1,300.00

80

300

X

Estimate Grand Total	\$ 1,300.00
----------------------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: