



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref: CS3/CTI22003326/Gqy3	
3 ANSON ROAD #16-00			Date: 11/04/2022	
SPRINGLEAF TOWERSINGAPORE 079909			Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBJ 3082S		Veh. Inspected	SKN 1866H
Policy No.			Coverage (\$)	0.00
Claim No.	SNM22D202454/C02/GBJ3082 S/LEWLC		Excess (\$)	0.00
Assign From	JENNY LEW		Assign Date	11/04/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/04/2022		Inspection Date	12/04/2022
Survey held at	7 SIN MING INDUSTRIAL ESTATE SECTOR C #01-82			
Repairer	GUAN AUTO SERVICE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				