



Your Ref: 21/22/22/VC05/025425

Date: 29th Apr 2022

Our Ref: CS1/LPC22003327/Evy3e2

M/s Lonpac Insurance Bhd

300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLS 1470T
INSURED VEHICLE: GBD 9660R
ACCIDENT DATE: 28/01/2022**

We thank you for your instruction on 11/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLS 1470T from M/s Impact Analysis Consulting Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLT 1470T.
- c) Colour damaged vehicle photographs of SLP 1470T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLP 1470L
Make & Model	: Mazda3 4-Door Sedan 1.5L SP.6EAT
Year of Registration	: 2017
Chassis Number	: JM6BM42A8G0347051
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.