Our Job Ref No : 305511877				ENGINEERING			
Date : 13.04.2022				ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
FINA	LIZAT	ION FORM			59 LO	yang Drive Singapore 508969	
То	: _		LKK		Fax:		
Attn	:		THEVAN				
Vehic	cle Reg	No. : SHC	8344U			09.04.2022	
The s	survey	and estimates o	f the repairs of the above-me	ntioned vehicle	are as follows		
Z	The	repair job shall b	ill to:	NTUC		SFD48X	
2.	The finalized amount shall be:						
	(a)		ter List discount				
	(b)	Labour Charge	s				
	(-/		By-Part Repair Cost				
	(c.)		air (if applicable) sum repair cost after Less: m Repair cost	, no seu-pillorene un		\$1,300.00	
3. 4.	We s		od for repairs:		rking days. f there is no r	eply from you within	
5.		king days	sistance	We	e confirm the	estimates and	
		(	Ab _	fina	alized amount		
	Signa	ture :		Sig	gnature:		
	Name	: CHIANG	U	Name : Thuyav			
	Tel	: 6214831	4	Da	ite : <u> </u>	21/4/22	
	Fax	: 6546815		_			
or Of	fficial	Jse Only					
	11	em	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rer	Rental Rate P/Day			YES			
	Loss of Income Paid		•	N			
	vey Fe			-			
LTA	Searc	h Fee	\$7.49/\$2.00	YES			
	dical F	ees (on behalf fapplicable)					
Med	river i						

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

**VEHICLE NO** 

SHC8344U

MAKE/REG

05.12.2019

DATE 09.04.2022 CHIANG/NTUC

TOYOTA PRIUS G4A	T	Unit Price	Amount
Parts Description/ Labour	Туре	One Frice	
		cut	<b>\$</b> 503.04
1		Cut	\$654.96
			\$378 32
			\$425.25
			\$55.00
			\$82.70
			\$52.90
			\$52.40
		6112.70	\$225.40
REAR BUMPER SIDE RETAINER LH/RH		,	\$22.00
REAR BUMPER CLIP		\$2.20	\$2,451.97
			\$612.99
S-100 M 100 M 100 M			
DISCOUNTED TOTAL			\$1,838.97
			¢c0.00
BOOTLID COMFORT & TEL NUMBER			\$60.00
BOOTLID COMFORT APP			\$40.00
			\$135.70
		\$0.10	\$212.13
Labour Charge			
_			\$700.00
_			\$600.00
	1		\$60.00
			\$60.00
TOTAL LABOUR			\$1,420.00
	SUB TOTAL 25.00% DISCOUNTED TOTAL  BOOTLID COMFORT & TEL NUMBER BOOTLID COMFORT APP BUMPER REVERSE SENSOR  Labour Charge Panel Beating Spray Painting Charge Check wiring and lighting Remove/Refix Reverse Sensor	REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT REAR CENTRE UNDER COVER REAR BUMPER REFLECTOR RH REAR BUMPER TOW COVER REAR TRUNK LOGO PRIUS REAR TRUNK LOGO HYBRID REAR BUMPER SIDE RETAINER LH/RH REAR BUMPER CLIP  SUB TOTAL 25.00% DISCOUNTED TOTAL  BOOTLID COMFORT & TEL NUMBER BOOTLID COMFORT APP BUMPER REVERSE SENSOR  Labour Charge Panel Beating Spray Painting Charge Check wiring and lighting Remove/Refix Reverse Sensor	REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT REAR CENTRE UNDER COVER REAR BUMPER REFLECTOR RH REAR BUMPER TOW COVER REAR TRUNK LOGO PRIUS REAR TRUNK LOGO HYBRID REAR BUMPER SIDE RETAINER LH/RH REAR BUMPER CLIP  SUB TOTAL 25.00% DISCOUNTED TOTAL  BOOTLID COMFORT & TEL NUMBER BOOTLID COMFORT APP BUMPER REVERSE SENSOR  \$0.10  Labour Charge Panel Beating Spray Painting Charge Check wiring and lighting Remove/Refix Reverse Sensor

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

8223 776 9

III | 1 | 22 | 6 | 5

L/S Yapaiv Zclays W

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" base

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comparison

LKK Auto Consultants hence notify the Repairer of the following:

- Third party survey is on a "Without Prejudice" basis
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: