Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Tokio Marine Insurance Singapore From: LKK Auto Consultants Pte Ltd Ltd

51 Ubi Ave 1 #01-25 20 McCallum Street Paya Ubi Industrial Park #09-01 Tokio Marine Centre

Singapore 408933 Singapore 069046

Attn: Yee Pei Li Date: 22 Apr 2022

Preliminary Advice

Insured : GBF5930C

Vehicle No

TP Vehicle Accident Date : SHA7935G : 09/04/2022

No

Make : HYUNDAI IONIQ HYBRID Assignment Date: 12/04/2022

Date of : 12/04/2022 Est. Duration of : 2 Inspection Repair

Inspection At: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

59 LOYANG DRIVE SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 2,662.84 **Revised Amount** :S\$ 1,408.60 Check Items (Estimated) :S\$ 0.00 Total :S\$ 1,408.60

Lump Sum Repair :S\$ 1,150.00

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.