



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM22003367/Uea3q2 Date: 20/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2339K	Veh. Inspected	SMU 8671X	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03YAW	Excess (\$)	0.00	
Assign From		Assign Date	12/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GB73105772	Colour	BLACK	
Odometer	175925 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	CONTINENTAL	7 mm	
L/H Front Tyre	185/65 R15	CONTINENTAL	7 mm	
R/H Rear Tyre	185/65 R15	CONTINENTAL	7 mm	
L/H Rear Tyre	185/65 R15	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2022	Inspection Date	12/04/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	