

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMU8671X

at Workshop m/s

R.

of

Insured:

SHA 2339K

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 98K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

0781
Vehicle: IN / OUT

Date:

Person Contacted:

27A 49237

Veh No: SMU8671X

Yr Regn: 31/08/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda freed Hybrid.c 1496

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

175925

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB7 3105772

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/04/22

D.O.I.

12/04/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep \$1K.

have video at folder

have GIA

2/5 \$3700 in Bond Alan

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Alu Ashar

Not Authorized
11/4/22
L/s \$3700
Hdays

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE No: SMU 8671X

1PC	REAR WINDSCREEN MOULDING	Alu	86.50	\$110.20	✓
1PC	TAILGATE	Body id	1207.20	\$1,699.20	✓
1PC	TAILGATE 'H' LOGO	Alu		\$45.00	✓
1PC	TAILGATE OUTER HANDLE GARNISH	11		\$450.00	X
2PCS	TAILGATE REFLECTORS @\$386.20	11		\$772.40	X
1PC	TAILGATE INNER LOCK	Tw		\$199.80	✓
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	De/CN		\$435.00	✓
1SET	TAILGATE INNER TRIM BOARD CLIPS	Alu		\$50.00	✓
1PC	TAILGATE WEATHERSTRIP	Tw	185.40	\$288.00	✓
1PC	REAR BUMPER	De	945.20	\$1,280.00	✓
2PCS	REAR BUMPER REFLECTORS @\$151.00	11		\$302.00	X
1SET	REAR BUMPER CLIPS	Alu		\$50.00	✓
1PC	REAR END PANEL OUTER	R		\$665.20	X
1PC	REAR END PANEL INNER	R		\$445.10	X
1PC	REAR END PANEL TOP GARNISH	Tw	266.30	\$341.10	✓
2PCS	TAILLAMPS @\$650.00	11		\$1,300.00	X
2PCS	TAILLAMP HOUSING PANELS @\$350.00	11	(202	\$700.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.00	11		\$790.00	X
				\$9,989.00	

S.NETT

1PC	REAR WINDSCREEN SEALANT	Alu	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	Alu	\$50.00	40
1PC	REAR END PANEL SEALANT	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	Shorted	\$280.00	200
1SET	REAR REVERSE CAMERA	11	\$450.00	X
1SET	REAR FLOOR PANEL INSULATOR	11	\$120.00	X

TO CEHCK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFX CUSHION UPHOLSTERY	\$120.00	80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	11 \$180.00	X
TO DISMANTLE & REFX REAR EXHAUST	11 \$100.00	X
TO SPRAY RUST PROOFING	\$100.00	40
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	550
TO PUTTY & SPRAY PAINTING	\$1,500.00	650

2-3470.4
202
2776.32

TOTAL \$15169.00

4626.32